

2024 ANNUAL INSPECTION REPORT FOR:

BLACK CREEK BOVINA DISTRICT

CENTER/GRAND CHUTE DISTRICT

CENTER VALLEY DISTRICT

DUCK CREEK DISTRICT

FREEDOM DISTRICT

NORTH LIBERTY DISTRICT

ONEIDA/HOBART DISTRICT

VANDENBROEK DISTRICT

PREPARED FOR:

OUTAGAMIE COUNTY DRAINAGE BOARD

PREPARED BY:

OUTAGAMIE COUNTY LAND CONSERVATION DEPARTMENT

3365 W. BREWSTER ST.

APPLETON, WI 54914

DATE: August 15th, 2024

The following pages report the information collected during the 2024 annual inspection of the 8 drainage districts located within Outagamie County. The annual inspections were conducted in the months of June and July by Sophia Krupka and Connor Hanson, Land Conservation Department and various drainage board members.

The larger drainage districts were split into multiple maps for clarity. The index follows this page.

The report contains the following information that has been sorted alphabetically by drainage district:

1. SUMMARY OF LINEAR FEATURES NEEDING MAINTENANCE

For each District:

2. MAP OF LINEAR FEATURES NEEDING MAINTENANCE
3. MAPS OF POINT FEATURES NEEDING MAINTENANCE
4. MAPS OF LEGAL DRAINS NOT BUFFERED

The electronic data for the 2024 Annual Inspection can be found at:

S:\LC\DrainageBoard\AnnualInspections\2024

2024 ANNUAL INSPECTION REPORT FOR OUTAGAMIE
COUNTY DRAINAGE DISTRICTS

2024 Maintenance Linear Features

755-Duck Creek Annex

Dredge

Length (ft)	Notes
482	
2608	
4346	
901	
485	
396	
Sum: 9217	

Other

Length (ft)	Notes
28	blocked culvert
65	good spot for possible green waterway
22	big muddy spot leading to ditch, needs seeding
948	waterway not vegetated/ needs seeding
113	major erosion gulley cutting into field and bank
Sum: 1176	

RemoveTrees

Length (ft)	Notes
85	
31	
126	
1663	
343	
2592	
509	
742	
116	
Sum: 6207	

SprayBrush

Length (ft)	Notes
231	
155	

755-Duck Creek Annex

SprayBrush

Length (ft)	Notes
234	willows
288	willows
226	willows
232	
802	
1179	
1335	willows
3517	
344	willows
Sum: 8542	

SprayCattails

Length (ft)	Notes
390	
55	
408	
658	
85	
1656	
121	
874	
Sum: 4247	

755-Duck Creek Northeast

Dredge

Length (ft)	Notes
49	
Sum: 49	

Other

Length (ft)	Notes
42	
7	Bank Erosion
Sum: 49	

RemoveTrees

Length (ft)	Notes
42	
6	
8	
1401	Open up corridor
Sum: 1457	

SprayBrush

Length (ft)	Notes
623	
Sum: 623	

755-Duck Creek Northwest

Other

	Length (ft)	Notes
	764	Bank erosion, possibly 2 stage
	800	Erosion and brush
	51	Crushed culvert
	127	Bank erosion not bad
	Sum: 1742	

RemoveTrees

	Length (ft)	Notes
	890	
	637	
	697	
	490	
	21	
	223	
	1	
	75	
	474	
	Sum: 3507	

SprayBrush

	Length (ft)	Notes
	104	
	301	
	262	
	485	
	86	
	Sum: 1238	

SprayCattails

	Length (ft)	Notes
	52	
	37	
	623	And some brush
	147	

755-Duck Creek Northwest

SprayCattails

Length (ft)	Notes
173	Remove trees
352	
Sum: 1383	

755-Duck Creek Southeast

Other

	Length (ft)	Notes
	39	Gulley
	94	Spray willow
	205	Spray willows
	2100	Good sit for 2stage with log vanes
	Sum: 2438	

RemoveTrees

	Length (ft)	Notes
	171	
	831	Keep an eye on removal trees north side of ditch
	Sum: 1002	

SprayBrush

	Length (ft)	Notes
	358	
	73	Spray willows
	97	Spray willows
	466	
	Sum: 994	

755-Duck Creek Southwest

Dredge

Length (ft)	Notes
398	
Sum: 398	

Other

Length (ft)	Notes
32	Gulley
Sum: 32	

Phragmites

Length (ft)	Notes
159	
Sum: 159	

SprayBrush

Length (ft)	Notes
569	
Sum: 569	

SprayCattails

Length (ft)	Notes
768	
Sum: 768	

756-Vandenbroek

Dredge

Length (ft)	Notes
454	
1427	
249	
479	
Sum: 2610	

Other

Length (ft)	Notes
1140	Thick brush, difficult to pass. Spray or mow
290	Good spot for grass waterway!
211	Buffer too thick to traverse, brush mow or spray
40	Tree down in buffer
79	Shed and retaining wall too close to ditch
79	Fence too close
Sum: 1840	

Phragmites

Length (ft)	Notes
197	
452	
Sum: 649	

RemoveTrees

Length (ft)	Notes
16	Fallen tree
19	Fallen tree
102	
300	
26	
199	
Sum: 663	

756-Vandenbroek

SprayBrush

	Length (ft)	Notes
	500	Willows
	133	Willows
	473	Willows
	99	
	440	
	301	Willows
	461	Willows and other brush
	1746	
	132	
	251	Willows
	295	

Sum: 4833

SprayCattails

	Length (ft)	Notes
	555	
	1686	
	191	
	2252	
	134	
	1525	
	1253	
	274	
	2100	
	200	
	530	
	716	
	830	
	312	
	2460	
	800	
	249	
	251	
	479	
	295	

Sum: 17093

757-Center/Grand Chute Central

RemoveTrees

Length (ft)	Notes
375	
Sum: 375	

SprayBrush

Length (ft)	Notes
81	
45	
122	
636	
1167	
303	
599	
525	
Sum: 3478	

SprayCattails

Length (ft)	Notes
138	
Sum: 138	

757-Center/Grand Chute East

Other

Length (ft)	Notes
35	
310	Grind brush- reestablish Cordoor
Sum: 345	

Phragmites

Length (ft)	Notes
83	
130	
792	
203	
105	
423	
78	
211	
Sum: 2025	

RemoveTrees

Length (ft)	Notes
1416	Many downed trees, reception was too poor
297	
Sum: 1712	

SprayBrush

Length (ft)	Notes
119	
853	
102	
117	
75	
26	
157	
32	
54	
111	

757-Center/Grand Chute East

SprayBrush

Length (ft)	Notes
452	
167	
114	
133	
Sum: 2515	

SprayCattails

Length (ft)	Notes
457	
715	
228	
317	
402	
104	
672	
38	
81	
435	
340	
121	
531	
199	
65	
77	
204	
Sum: 4985	

757-Center/Grand Chute West

Phragmites

Length (ft)	Notes
91	
52	
75	
78	
Sum: 297	

SprayBrush

Length (ft)	Notes
152	
246	
53	
32	
89	
97	
56	
196	
Sum: 921	

SprayCattails

Length (ft)	Notes
80	
18	
339	
259	
100	
Sum: 796	

758-Black Creek/Bovina

RemoveTrees

Length (ft)	Notes
2951	Open up corridor some spots are ok others aren't
855	
377	
547	
1874	
2394	
2903	Open up corridor some spots are ok others aren't
5269	Open up corridor
2337	
403	
170	
441	Trees falling into ditch in spots
Sum: 20521	

SprayBrush

Length (ft)	Notes
37	
Sum: 37	

759-Freedom North

Phragmites

Length (ft)	Notes
244	
287	
81	
49	
Sum: 662	

SprayBrush

Length (ft)	Notes
101	
Sum: 101	

SprayCattails

Length (ft)	Notes
339	
538	
487	
228	
296	
513	
175	
Sum: 2575	

759-Freedom South

Phragmites

Length (ft)	Notes
90	
148	
Sum: 238	

SprayBrush

Length (ft)	Notes
115	Remove willows?
Sum: 115	

SprayCattails

Length (ft)	Notes
1048	
627	
915	
1194	
1369	
1085	
217	
282	
385	
489	
358	
466	
1292	
1455	
Sum: 11180	

760-North Liberty

Other

Length (ft)	Notes
0	Parts of a bridge
Sum: 0	

Phragmites

Length (ft)	Notes
202	
Sum: 202	

RemoveTrees

Length (ft)	Notes
256	
132	
94	
100	Dead ash
2248	Boxelders along ditch
545	Trees falling into ditch
324	
861	
401	
709	
233	
86	
12	
1513	Dead ash
864	
Sum: 8377	

SprayBrush

Length (ft)	Notes
214	
353	
450	Small patches of brush
734	

760-North Liberty

Sum: 1751

SprayCattails

Length (ft)	Notes
899	Some cattails
647	
1862	
Sum: 3409	

762-Center Valley

Other

Length (ft)	Notes
44	Burn brush/wood scraps
Sum: 44	

Phragmites

Length (ft)	Notes
38	
Sum: 38	

RemoveTrees

Length (ft)	Notes
909	
244	Trees and sediment blockage
22	
978	
993	
1633	
1788	
345	
85	
Sum: 6996	

SprayBrush

Length (ft)	Notes
848	
762	
983	
3477	Spot spray brush, a few patches throughout
1610	
1817	
345	
85	
Sum: 9927	

763-Oneida/Hobart Brown County

Phragmites

Length (ft)	Notes
515	
125	
124	
Sum: 765	

SprayBrush

Length (ft)	Notes
434	
139	Brush phrag and cattails
277	Also cattails
165	
755	Willows
94	Willows
124	Brush phrag and cattails
Sum: 1989	

763-Oneida/Hobart North

Other

Length (ft)	Notes
227	Needs waterway
Sum: 227	

Phragmites

Length (ft)	Notes
371	
67	
363	
299	
Sum: 1100	

SprayBrush

Length (ft)	Notes
544	Willows
132	Willows
566	
1148	Willows
Sum: 2391	

SprayCattails

Length (ft)	Notes
348	
231	
557	
1565	
1347	
443	
432	
1341	
2131	
1903	
72	
1018	And phrag
1063	

763-Oneida/Hobart North

SprayCattails

Length (ft)	Notes
871	
1125	
347	
1148	And phrag
Sum: 15942	

763-Oneida/Hobart South

Dredge

Length (ft)	Notes
965	
3365	
Sum: 4330	

Phragmites

Length (ft)	Notes
131	
66	
Sum: 197	

SprayBrush

Length (ft)	Notes
90	
Sum: 90	

SprayCattails

Length (ft)	Notes
502	
517	
106	
124	
539	
219	
512	
2404	
829	
1821	
Sum: 7573	